Bob Anthony
Commissioner

Todd Hiett
Commissioner

Dana Murphy
Commissioner

OKLAHOMA
Corporation Commission

P.O. BOX 52000
OKLAHOMA CITY OKLAHOMA 73152-2000

255 Jim Thorpe Building
Telephone: (405)521-2302
FAX: (405)521-3099

OIL & GAS CONSERVATION DIVISION

Tim Baker, Division Director

Thursday, August 17, 2017

Multiple Well Transfer Request: 1073MW form

From: Midstates Petroleum Company LLC, #23079

To: Prairie Gas Company of Oklahoma LLC, #24073

All wells on the submitted list were approved, with the following exceptions:

The lined through well on the list was not transferred:

34 wells were transferred

Instructions

A. Please type or print using black or blue ink.
B. Form must be signed by former operator and new operator.
C. Signatories must be listed on their company's Form 1006B.
D. Fill in the complete legal description on back page or successive pages.
E. Direct questions to Well Records at (405) 521-2271.

OKLAHOMA CORPORATION COMMISSION
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000

Transfer of Operator
Mutiple Oil and/or Gas Wells
OAC 165:10-1-15

This form must be filed with the OCC **within 30 days of transfer** of the wells.

Form 1073MW
Rev. 2017 - Front Page

RECEIPT 1801750009
Date: 08/15/2017 Time: 13:03
FEE: $250.00
OAC 165:5-3-1(b)(1)(O)
(SEE BACK PAGE FOR PAYMENT INFORMATION)
$250.00

CURRENT OPERATOR

OCC/OTC No. 23079

Name: Midstates Petroleum Company LLC
Address: 321 South Boston Avenue, Suite 1000
City: Tulsa State: OK Zip: 74103
FAX No./E-mail: ky.nichols@midstatespetroleum.com

I verify that I am the legal operator of record with authority to transfer operatorship of these wells, that the facts presented herein are true and correct, and that I have completed this form and attached all documents as required by the above instructions.

No. of wells listed: 35 -1/34

(Signatory must be listed on company's Form 1006B Operator's Agreement)

Signature: Ky Nichols Vice President of EHS (918) 947-4620
Name & Title (Print or Type) (AC) Phone

Signed and sworn to before me this 26 day of July, 2017

Notary Public

My Commission Expires: 11-21

MARILYN M. BLEVINS NOTARY PUBLIC #01001515 EXP. 03/11/21 STATE OF OKLAHOMA

NEW OPERATOR

OCC/OTC No. 24073

Name: Prairie Gas Company of Oklahoma, L.L.C.
Address: P. O. Box 701228
City: Tulsa State: OK Zip: 74170
FAX No./E-mail: srackley@pge-llc.com

Being the new operator, as of the effective date of transfer, I accept the facts presented as being true and correct and accept the operational responsibility for the wells on the described property.

No. of wells listed: 35 -1/34

(Signatory must be listed on company's Form 1006B Operator's Agreement)

Signature: Steve Rackley Operations Officer 918-734-7727
Name & Title (Print or Type) (AC) Phone

Signed and sworn to before me this 26 day of July, 2017

Notary Public

My Commission Expires: 11-21

MARILYN M. BLEVINS NOTARY PUBLIC #01001515 EXP. 03/11/21 STATE OF OKLAHOMA

DO NOT WRITE INSIDE THIS BOX

The **effective date of transfer** is the **date that the transfer is approved** by the Commission.

Use **this** form to transfer **10 or more** oil or gas wells. Use **Form 1073** to transfer **single** oil and gas wells.

I verify under oath that I have exercised **due diligence** in attempting to locate the current operator of record according to OCC records, who has **abandoned** the above wells/leases and **cannot be located** to obtain a signature. I have attached **certified copies of the recorded lease(s) or assignment(s)**, **or certified copies of a journal entry of judgment** or **bankruptcy proceeding** pursuant to OAC 165:10-1-15(b).

_____
Signature

Signed and sworn to before me this _____ day of _____, _____.

_____
Notary Public

My commission expires: _____

FOR OCC USE ONLY

	Surety	Approved Date
Well Records Review:	AUG 17 2017	AUG 17 2017 WELL RECORDS APPROVED

By processing this Form 1073MW, the Oklahoma Corporation Commission has approved the contents thereof as to **form only**. The Oklahoma Corporation Commission does **not** warrant that the **facts provided by the operator** are **true**.

Transfer is **not effective until approved** by the **Well Records Department**.

If unable to print form correctly, click "Page Layout" and decrease the "Scale" as needed (try 85% first) to print correctly.

Use this form to transfer **10 or more** oil or gas wells. Use **Form 1073** to transfer **single** oil or gas wells.

Print this form in "**Landscape**" (**wide**) (**horizontal**) orientation only.

LIST MULTIPLE WELLS ON PAGE 3 AND SUBSEQUENT PAGES OF THIS FORM

OPERATOR NAME / NUMBER:
Prairie Gas Company of Oklahoma, L.L.C./

TOTAL NUMBER OF WELLS LISTED (MUST MATCH NUMBER OF WELLS IN "SIGNATURE BOX" ON FIRST PAGE):
35 - 1 = 34

CODES -- FOR THE WELLS ON YOUR TRANSFER LIST, SPECIFY A "WELL STATUS" CODE FROM THE CHOICES BELOW:
ND (new drill), SP (spud), AC (active), TA (temporarily abandoned/not plugged), TM (terminated order/UIC well not plugged)

This form must be sent, along with payment, to the Cashier at either the Jim Thorpe Office Building in Oklahoma City or the OCC office in Tulsa.

OKLAHOMA CITY MAILING ADDRESS:
Oklahoma Corporation Commission
Attention: Cashier's Office
P.O. Box 52000
Oklahoma City, OK 73152-2000
(checks or money orders only)

HAND-DELIVERY STREET ADDRESS:
The Jim Thorpe Office Building
(The Cashier is on the First Floor)
2101 N. Lincoln Blvd.
Oklahoma City, OK 73105
(cash, checks or money orders only)

TULSA MAILING ADDRESS:
Oklahoma Corporation Commission
Attention: Court Clerk's Office
440 S. Houston Ave., Suite 114
Tulsa, OK 74127
(checks or money orders only)

CHECKLIST FOR WELL LIST ENTRY BY COMPUTER:

1. USE "ALL CAPS" TEXT (NO "LOWER CASE" TEXT). USE SINGLE NUMBERS FOR "HALF" SECTIONS (for example, "E2").

2. SORT WELLS IN ORDER OF "LOWEST TO HIGHEST" API NUMBER; HIGHLIGHT DATA TO SORT, THEN "SORT" IT (COLUMN HEADINGS, COLUMNS OR ROWS CANNOT BE HIGHLIGHTED OR SORTED; ONLY THE WELL DATA THAT YOU ENTERED CAN BE HIGHLIGHTED AND SORTED).

3. USE LEADING ZERO's (AS APPLICABLE) FOR SECTION, TOWNSHIP AND RANGE (i.e., 01/01N/22E).

4A. PRIMARY PRINTING METHOD: SET A "PRINT AREA" AROUND YOUR LIST OF WELLS TO ALLOW EXCEL TO CORRECTLY SET THE PAGE RANGE IN THE PRE-DEFINED "HEADER" OF THE FILE.

4B. ALTERNATE PRINTING METHOD: IF UNABLE TO SET A "PRINT AREA" -- DELETE ALL ROWS (THAT HAVE PRE-DEFINED SOLID BORDERS) BELOW THE LAST WELL YOU LISTED. THIS WILL ALLOW EXCEL TO CORRECTLY SET THE PAGE RANGE IN THE PRE-DEFINED "HEADER" OF YOUR FILE.

5. E-MAIL A COURTESY COPY OF YOUR COMPLETED EXCEL FILE TO THE OCC WELL RECORDS DEPT. CALL OUR WELL RECORDS DEPT. AT (405) 521-2271 TO OBTAIN THE CURRENT E-MAIL ADDRESS.

NOTE

YOUR WELL LIST, NOTARIZED 1073MW FORM AND PAYMENT MUST STILL BE MAILED OR DELIVERED TO ONE OF THE ADDRESSES LISTED ABOVE.

If unable to print form correctly, click "Page Layout" and decrease the "Scale" as needed (try 85% first) to print correctly.

Use this form to transfer 10 or more wells. Use Form 1073 to transfer single oil or gas wells.

Print this form in "Landscape" (wide) (horizontal) orientation only.

(Sort by API Number) (Use "ALL CAPS" text)

OCC USE	10-Digit API Number (NO DASHES) (NO SUFFIXES)	Well Name (UPPER CASE letters only)	Well # (letters: UPPER CASE)	Well Class: (OIL, GAS or DRY)	Well Status: (ND, SP, AC, TA or TM)	SEC	TWP (i.e. 02N)	RGE (i.e. 05E)	CM? If not, leave blank.	Qtr	Qtr	Qtr	Qtr	COMMENTS
	(ALL CAPS)		(ALL CAPS)	[REQUIRED]			(ALL CAPS)			(UPPER CASE LETTERS)				
✓	3508123844	TIDWELL ~~1H~~	1H	GAS	AC	22	15N	03E		NW	NW	NW	SW	
✓	3508123848	FALCON ~~1H~~	1H	GAS	AC	08	13N	03E		NW	NW	NW	NW	
✓	3508123851	WALLACE ~~1H~~	1H	GAS	AC	8 ~~07~~	13N	03E		NW	NW	NW	NW	
✓	3508123853	WINSTON ~~1H~~	1H	GAS	AC	23	15N	03E		NE	NW	NW	NW	
✓	3508123866	ARLIE ~~1H~~	1H	GAS	~~AC~~ TA	10	15N	03E		SE	NW	SW	SW	
✓	3508123880	BRUCE ~~1H~~	1H	GAS	AC	23 ~~14~~	15N	03E		NE	NW	NW	NW	
✓	3508123883	SPRING ~~1H~~	1H	GAS	AC	26	15N	03E		NE	NE	NE	NE	
✓	3508123886	BERNARD ~~1H~~	1H	GAS	~~AC~~ TA	11 ~~03~~	15N	03E		NW	NW	NW	NW	
✓	3508123895	CLINT ~~1H~~	1H	GAS	~~AC~~ TA	~~34~~	15N ~~16N~~	03E		NE	NE	NE	NE	
✓	3508123900	SPEARS ~~1H~~	1H	GAS	~~AC~~ TA	~~35~~	15N ~~16N~~	03E		NE	NE	NE	NE	
✓	3508123902	RAINWATER CRANE ~~1~~	1-H	GAS	~~AC~~ TA	34	15N	03E		NE	NW	NW	NE	
✓	3508123915	SLATER ~~1H~~	1H	GAS	~~AC~~ TA	11	15N	03E		NW	NW	NW	NW	
✓	3508123916	GREENFIELD ~~1H~~	1H	GAS	~~AC~~ TA	3 ~~02~~	15N	03E		NE	NE	NE	NE	
✓	3508123918	DAISY ~~1H~~	1H	GAS	~~AC~~ TA	04	14N	03E		NW	NW	NW	NW	
✓	3508123926	JEWEL ~~1H~~	1H	GAS	AC	3 ~~09~~	14N	03E		SW	SW	SW	SW	
✓	3508123930	HOVER	1H	GAS	AC ~~TA~~	6 ~~12~~	13N	3E ~~02E~~		SW	SW	SW	SW	
✓	3508123932	CHUCKAHO STATE ~~1H~~	1H	GAS	~~AC~~ TA	16	14N	03E		SE	SE	SE	SE	~~API: 3508123932-A~~
✓	3508123937	WILLOW ~~1H~~	1H	GAS	~~AC~~ TA	21 ~~35~~	15N	03E		SE	SW	SW	SW	
✓	3508123938	DEEP FORK ~~1H~~	1H	GAS	~~AC~~ TA	11 ~~15~~	14N	03E		NE	SE	SE	SE	
	~~3508123939~~	~~PORTMAN 1H~~	1H	2D Not Com ~~GAS~~	AC	09	13N	03E		E2	SE	NE	NE	Inj well - transfer must be on 1073I
✓	3508123942	SHERMAN ~~1H~~	1H	GAS	AC	25 ~~24~~	15N	03E		NW	NE	NW	NW	
✓	3508123948	MAGGIE ~~1H~~	1H	GAS	AC	25	15N	03E		NW	NE	NW	NW	
✓	3508123951	ALLEN TRUST ~~1H~~	1H	GAS	~~AC~~ TA	36	15N	03E		SW	SW	SW	SW	
✓	3508123952	GARDNER ~~1H~~	1H	GAS	~~AC~~ TA	3 ~~10~~	14N	03E		SW	SW	SW	SW	

24
-1/23

(Sort by API Number) (Use "ALL CAPS" text)

OCC USE	10-Digit API Number (NO DASHES) (NO SUFFIXES)	Well Name (UPPER CASE letters only)	Well # (letters: UPPER CASE)	Well Class: (OIL, GAS or DRY)	Well Status: (ND, SP, AC, TA or TM)	SEC	TWP (i.e. 02N)	RGE (i.e. 05E)	CM? If not, leave blank.	Qtr	Qtr	Qtr	Qtr	COMMENTS
	(ALL CAPS)	(ALL CAPS)	[REQUIRED]			(ALL CAPS)			(UPPER CASE LETTERS)					
✓	3508123954	JOYCE 1H	1H	GAS	AC ~~TA~~	31 ~~05~~	14N ~~13N~~	03E		SE	SE ~~NE~~	SE	SE ~~SW~~	
✓	3508123960	CHARLOTTE 1H	1H	GAS	AC	31 ~~06~~	14N ~~13N~~	03E		SE	SE	SE	SE	
✓	3508123963	COLLEEN 1H	1H	GAS	AC	03	14N	03E		SW	SW	SW	SW	
✓	3508123966	JOSHUA 1H	1H	GAS	AC	32	15N	04E		NE	SE	NE	NE	
✓	3508123970	BLAKE 1H	1H	GAS	AC ~~TA~~	31	15N	04E		NW	NE	NE	NE	
✓	3508123972	WESTLAKE 1H	1H	GAS	AC	31 ~~30~~	15N	04E		NW	NE	NE	NE	
✓	3508123987	BAY 1H	1H	GAS	AC ~~TA~~	20 ~~17~~	13N	03E		NW	NW	NW	NW	
✓	3508124000	CANYON 1H	1H	GAS	~~TA~~ AC	32 ~~06~~	15N ~~14N~~	04E		NE	SW	SW	SW	
✓	3508124002	TURNPIKE 1H	1H	GAS	AC	05	14N	04E		NW	NE	NE	NE	
✓	3508124044	TURNER 1H	1H	GAS	AC	6 ~~01~~	14N	03E		NW	SW	SW	SW	
✓	3508124046	HUMBLE 1H	1H	GAS	AC	6 ~~12~~	14N	03E ~~04E~~		NW	SW	SW	SW	

11

Janie Hlinicky

From: Janie Hlinicky
Sent: Thursday, August 17, 2017 3:28 PM
To: 'KY.nichols@midstatespetroleum.com'; 'SRACKLEY@PGE-LLC.COM'
Subject: Mass Well Transfer
Attachments: Midstates Petr mass transfer_08172017.pdf

To Whom It May Concern,

We have approved the transfer of 34 wells on the attached 1073MW from Midstates Petroleum Company LLC (23079) to Prairie Gas Company of Oklahoma LLC (24073). The lined-through well was not transferred. That well is an injection well and must be submitted on Form 1073I.

Sincerely,
Janie Hlinicky
Oklahoma Corporation Commission
Well Records Section
Phone: 405.521.2271
Fax: 405.522.0854
j.hlinicky@occemail.com
Oklahoma Corporation Commission

There are new forms for transfers. 1073 for single well, 1073MW for 10+ wells, 1073I for single injection well, 1073IMW for 10+ injection wells. Fees for transfers went into effect August 25, 2016. The amounts of the fees are on the forms.