A. Please type or print using black ink. B. Form must be signed by former operator and new operator. C. Outline boundaries of lease and spot well being transferred. D. Attach 1002A for well. E. Direct questions to Well Records (405) 521-2275. API Nc 051-22788 OTC Prod. Unit No. Location E2 1/4 W2 1/4 Ft FSL of 1000 Ft FWL of 500	LAHOMA CORPORATION COMMISSION Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, OK 73152-2000 Transfer of Operator OAC 165:10-1-15 051-104232 Twp 5N Rge. 7W County	3 — 1 — 2 Form 1078 Rev. 2099 5280 ft 2310' 1650' 990' 330'
Qtr Sec 1,320 Qtr Sec 560 Current Well Mame/Number Marshall-Craddo Original Well Mame/Number Unit Name (if applicable) Well Class: XOIL GAS DRY Producing	ock #1-22	2310' 1650' 990' 330' Locate Well On Grid Above
Sycamore & 2nd Bromide The effective date of transfer of this well, for the purposes of Commission records, is the date that the transfer is approved by the Commission. OCC No. OCC No.		
	NEW OPERATOR Name Address	Gomaco Operating, Society Control of Control
City State Zin	Phone No. I verify that I am transfer operator Signature Name & Title (Tourish and swood) Notary STATE Commission My commission	
according to OCC records, who has abandoned the abov I have attached a copy of the certified recorded assig * APPROVED COPY AVAILABLE ON OCC WEBSITE. * Signed and sworn to before me this day of	e well/lease and cannot be loca nment of lease.	
My commission expires: FOR OCC USE ONLY Surety Dept. Approved Rejected Date	Well Records Dept. App	WELL RECORDS

NOTE: By processing this Form 1073, the Oklahoma Corporation Commission has approved the contents thereof as to form only. Oklahoma Corporation Commission does not warrant that the facts provided by the operator are true. **Form is not approved until approved by Well Records.**