OKLAHOMA CORPORATION COMMISSION

Form 1001A Rev. 2012

SPUD 11/19/13
* (state the **EXACT DATE**that the well was spudded)

Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

NOTIFICATION OF WELL SPUD

(OAC 165:10-3-2)

OPERATOR		INSTRUCTIONS
	C/OCC //307	PLEASE TYPE OR USE BLACK INK
Address 2217 Cardnal Rd Pro	one 580 504 0074	
city ardmore State oK	Zip 73401	·
WELL Name/No. Rose(2-23 AP No. NE 1/4 SE 1/4 SE 1/4 SW Sec. 23 Twp. 2S Rge. 2W County	1010 15979.	Complete and mail within 14 (fourteen) days after spudding to the Corporation Commission at the address below: Oklahoma Corporation Commission Oil & Gas Conservation Division P.O. Box 52000 Oklahoma City, Oklahoma 73152-2000
Name		
Address SAMP G5 960UP.		
City State	Zip	
SURFACE CASING CEMENTED BY (if job completed) Name Address	one	RECEIVED
No. City State		NOV 21 2013
Date	J-19	OKLAHOMA CORPORATION COMMISSION
Cemented		
I declare that I have knolwedge of the contents of this report and am authorized by my organization to make this report, which was prepared by me or under my supervision and direction, with the data and facts stated herein to be true, correct, and complete to the best of my knowledge and belief.		
Oal Ball Paul Signature Print	Durton Manac nt or Type Name and Title	580 50 4 00 7 4 Phone No.
Note: The district manager or field inspector shall be notified at least twenty-four (24) hours in advance, prior to commencing spudding operations.		

DISTRICT I

115 West 6th Street
Post Office Box 779
Bristow, OK 74010-0779
(918) 367-3396
OGBristowOffice@occemail.com

DISTRICT II

101 South 6th Street
Post Office Box 1107
Kingfisher, OK 73750-1107
(405) 375-5570
OGKingfisherOffice@occemail.com

DISTRICT III

1020 Willow Street Post Office Box 1525 Duncan, OK 73533 (580) 255-0103

OGDuncanOffice@occemail.com

DISTRICT IV

1400 Hoppe Blvd. Suite "D" Ada, OK 74820-3437 (580) 332-3441

OGAdaOffice@occemail.com