

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35153235920000

Completion Report

Spud Date: December 29, 2016

OTC Prod. Unit No.:

Drilling Finished Date: December 30, 2016

1st Prod Date:

Completion Date: December 30, 2016

Drill Type: HORIZONTAL HOLE

Well Name: SANDER 36-21N-18W 1H

Purchaser/Measurer:

Location: WOODWARD 36 21N 18W
SE SE SW SW
240 FSL 1245 FWL of 1/4 SEC
Derrick Elevation: 1799 Ground Elevation: 1774

First Sales Date:

Operator: DEVON ENERGY PRODUCTION CO LP 20751

333 W SHERIDAN AVE
OKLAHOMA CITY, OK 73102-5010

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	There are no Location Exception records to display.		There are no Increased Density records to display.	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20	94	K-55	110		27	SURFACE

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 405

Packer		Plug	
Depth	Brand & Type	Depth	Plug Type
There are no Packer records to display.		285'	CEMENT

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
There are no Initial Data records to display.										
Completion and Test Data by Producing Formation										

Formation Name: MISSISSIPPIAN

Code: 359MSSP

Class: PLUG AND ABANDON

Formation	Top
MISSISSIPPIAN	0

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

THE OPERATOR HAS SAID THAT AFTER THEY HAD SET THE CONDUCTOR PIPE AND BECAUSE OF THE WELL INSTABILITY THE FIELD PEOPLE HAD TO STOP DRILLING AND CALLED THE CEMENT COMPANY TO PURE 1488 SAX OF CEMENT AND PLUG THE WELL ON 12/30/16. THERE WAS NO SURFACE CASING SET BUT THE CONDUCTOR PIPE WAS LEFT IN THE HOLE WHEN WAS BEING PLUGGED.

FOR COMMISSION USE ONLY

1135501

Status: Accepted