

Oklahoma Corporation Commission
 Oil & Gas Conservation Division
 Post Office Box 52000
 Oklahoma City, Oklahoma 73152-2000
 Rule 165: 10-3-25

Form 1002A

API No.: 35119042220001

Completion Report

Spud Date: November 24, 1954

OTC Prod. Unit No.: 119-31386

Drilling Finished Date: December 07, 1954

1st Prod Date: December 14, 1954

Amended

Completion Date: December 22, 1954

Amend Reason: CHANGE OF OPERATOR

Drill Type: STRAIGHT HOLE

Well Name: MOHLER 2

Purchaser/Measurer:

Location: PAYNE 35 18N 4E
 C SE4 NW4 SE4
 1650 FSL 990 FWL of 1/4 SEC
 Derrick Elevation: 954 Ground Elevation: 946

First Sales Date:

Operator: INTERNATIONAL ENERGY COMPANY LLC 23556

1801 E 71ST ST
 TULSA, OK 74136-3922

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
There are no Location Exception records to display.	

Increased Density	
Order No	
There are no Increased Density records to display.	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	32	J-55	302		250	SURFACE
PRODUCTION	5 1/2	15.5		4042		1100	2946

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 4050

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
There are no Initial Data records to display.										

Completion and Test Data by Producing Formation

Formation Name: VIOLA

Code: 202VIOL

Class: OIL

Spacing Orders

Order No

Unit Size

There are no Spacing Order records to display.

Perforated Intervals

From

To

4026

4033

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments

There are no Fracture Treatments records to display.

Formation

Top

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

OIL SHUT IN PRODUCER

FOR COMMISSION USE ONLY

Status: Accepted

1135761