

**Instructions**

- A. Please type or print using black ink.
- B. Form must be signed by former operator and new operator.
- C. Outline boundaries of lease and spot well being transferred.
- D. Attach 1002A for well.
- E. Questions should be directed to Well Records (405) 521-2275.

**OKLAHOMA CORPORATION COMMISSION**


Oil & Gas Conservation Division  
 Post Office Box 52000  
 Oklahoma City, OK 73152-2000

**611030613**

Form 1073  
 Rev. 2001

**Transfer of Operator**  
 OAC 165:10-1-15

API No. <b>037 22364</b>		OTC Prod. Unit No. <b>037-5858V</b>	
Location <b>1/4 SW 1/4 SW 1/4 NW 1/4</b>		Sec. <b>12</b>	Twp. <b>18N</b> Rge. <b>8E</b>
Ft FSL of Qtr Sec <b>330</b>	Ft FWL of Qtr Sec <b>330</b>	County <b>CREEK</b>	
Current Well Name/No. <b>WA, SIDWELL #4</b>			
Original Well Name/No. <b>SAME</b>			
Unit Name (if applicable)			



Locate Well On Grid Above

Well Class:  Oil  Gas  Dry  Plugged

Producing formation(s) <b>RED FORK</b>	OTC No. <b>15814</b>
Oil Transporter/Purchaser <b>DUKE ENERGY</b>	OTC No. <b>00099</b>
Gas Measurer <b>ASSOCIATED NAT GAS INC.</b>	

The effective date of transfer of this well for the purposes of Commission records, is the date the transfer is approved by the Commission.

**CURRENT OPERATOR**

Name <b>LUCRE OIL CO.</b>	OCC No. <b>19727</b>
Address <b>201 So. 33 #911</b>	
City <b>MUSKOGEE</b>	State <b>OK</b> Zip <b>74401</b>
Phone No. <b>918 682 2795</b>	FAX No.
I verify that I am the legal operator of record with authority to transfer operatorship of this well.	
Signature <b>G.H. Fitzgerald</b>	
Name & Title (Typed or Printed) <b>G.H. Fitzgerald OWNER</b>	
Signed and sworn to before me this <b>23</b> day of <b>Nov</b> 2006	
My Commission Expires <b>March 06, 2007</b>	
Commission # <b>0300338</b>	
Notary Public	
My commission expires: <b>3-6-2007</b>	

**NEW OPERATOR**

Name <b>Well Renewal Inc.</b>	OCC No. <b>21782</b>
Address <b>320 S. Boston Suite 1026</b>	
City <b>TULSA</b>	State <b>OK</b> Zip <b>74103</b>
Phone No. <b>918.585.5101</b>	FAX No. <b>918.512.4337</b>
Being the new operator, as of the effective date and time of transfer accept the facts presented as being true and correct and accept the operational responsibility for the well on the described property.	
Signature <b>E.N. Gray II</b>	
Name & Title (Typed or Printed) <b>Everett Willard Gray II, CEO</b>	
Signed and sworn to before me this <b>23</b> day of <b>Nov</b> 2006	
My Commission Expires <b>01-17-2010</b>	
Commission # <b>06000656</b>	
Notary Public	
My commission expires: <b>01-17-2010</b>	

I verify under oath that I have exercised due diligence in attempting to locate the current operator of record according to OCC records, who has abandoned the above well/lease and cannot be located to obtain signature. I have attached a copy of the certified recorded assignment of lease.

Signed and sworn to before me this \_\_\_\_\_ day of \_\_\_\_\_

My commission expires: \_\_\_\_\_

**FOR OCC USE ONLY** **NOV 08 2006**

Surety Dept.  Approved  Rejected Date \_\_\_\_\_

**Notary Public**  
 State of Oklahoma  
**DANIELLE DAVIS**  
 TULSA COUNTY  
 COMMISSION #06000656  
 Comm. Exp. 01-17-2010

Signature

Notary Public

Well Records Dept.

Approved  Rejected

Date

**NOV 09 2006**

**WDMS**

NOTE: By processing this Form 1073, the Oklahoma Corporation Commission has approved the contents thereof as to form only. Oklahoma Corporation Commission does not warrant that the facts provided by the operator are true. Form is not approved until approved by Well Records.