

Instructions

- A. Please type or print using black ink.
- B. Form must be signed by former operator and new operator.
- C. Outline boundaries of lease and spot well being transferred.
- D. Attach 1002A for well.
- E. Questions should be directed to Well Records (405) 521-2275.


OKLAHOMA CORPORATION COMMISSION

Oil & Gas Conservation Division  
 Post Office Box 52000  
 Oklahoma City, OK 73152-2000

12-13-12

Form 1073 Rev. 2001

**Transfer of Operator**  
 OAC 165:10-1-15



Locate Well On Grid Above

API No. <b>141-20316-A</b>	OTC Prod. Unit No.		
Location <b>SE 1/4 SW 1/4 NW 1/4 SW 1/4</b>	Sec. <b>4</b>	Twp. <b>5S</b>	Rge. <b>14W</b>
Ft FSL of Qtr Sec <b>1635'</b>	Ft FWL of Qtr Sec <b>862'</b>	County <b>TULLMAN</b>	
Current Well Name/No. <b>STEWART - WELFARE #1</b>			
Original Well Name/No. <b>A/A</b>			
Unit Name (if applicable) <b>N/A</b>			

Well Class:  Oil  Gas  Dry  Plugged

Producing formation(s) <b>GUNSITE 1691'-1693'</b>	OTC No.
Oil Transporter/Purchaser	OTC No.
Gas Measurer	OTC No.

The effective date of transfer of this well for the purposes of Commission records, is the date the transfer is approved by the Commission.

CURRENT OPERATOR

Name <b>Helton Oil Co.</b>	OCC No. <b>15136-0</b>
Address <b>P.O. Box 7283</b>	
City <b>Edmond</b>	State <b>OK</b> Zip <b>73083</b>
Phone No. <b>405-615-5500</b>	FAX No. <b>bigjohnhelton@gmail.com</b>
I verify that I am the legal operator of record with authority to transfer operatorship of this well.	
Signature <b>John R. Helton</b>	
Name & Title (Typed or Printed) <b>John R. Helton, OWNER</b>	
Signed and sworn to before me this <b>13<sup>th</sup></b> day of <b>December, 2012</b>	
Notary Public <b>[Signature]</b>	
My commission expires: <b>9/24/16 #15241</b>	

NEW OPERATOR

Name <b>Superior Oil and Gas Co. of OKLA.</b>	OCC No. <b>21997-0</b>
Address <b>844 S. Walbaum Rd.</b>	
City <b>Calumet</b>	State <b>OK</b> Zip <b>73014</b>
Phone No. <b>405-884-2080</b>	FAX No. <b>509@pldi.net</b>
Being the new operator, as of the effective date and time of transfer accept the facts presented as being true and correct and accept the operational responsibility for the well on the described property.	
Signature <b>[Signature]</b>	
Name & Title (Typed or Printed) <b>Daniel H. Lloyd, Jr., President</b>	
Signed and sworn to before me this <b>13<sup>th</sup></b> day of <b>December, 2012</b>	
Notary Public <b>[Signature]</b>	
My commission expires: <b>9/24/16 #15241</b>	

I verify under oath that I have exercised due diligence in attempting to locate the current operator of record according to OCC records, who has abandoned the above well/lease and cannot be located to obtain signature. I have attached a copy of the certified recorded assignment of lease.

Signature

Signed and sworn to before me this \_\_\_\_\_ day of \_\_\_\_\_

My commission expires: \_\_\_\_\_

Notary Public

DEC 19 2012

FOR OCC USE ONLY

Surety Dept.  Approved  Rejected Date **DEC 19 2012**

Well Records Dept.  Approved  Rejected Date **APPROVED**

WELL RECORDS

NOTE: By processing this Form 1073, the Oklahoma Corporation Commission has approved the contents thereof as to form only. Oklahoma Corporation Commission does not warrant that the facts provided by the operator are true. Form is not approved until approved by Well Records.

Per Sally Shipley  
OARD