

**Instructions**

- A. Please type or print using black ink.
- B. Form must be signed by former operator and new operator.
- C. Outline boundaries of lease and spot well being transferred.
- D. Attach 1002A for well.
- E. Direct questions to Well Records (405) 521-2275.

**OKLAHOMA CORPORATION COMMISSION**

Oil & Gas Conservation Division  
 Post Office Box 52000  
 Oklahoma City, OK 73152-2000

Transfer of Operator  
 OAC 165:10-1-15

2/17/15 3  
 Form 1073  
 Rev. 2009

API No <b>A 083-21624</b>		OTC Prod. Unit No. <b>083-70330</b>	
Location <b>C 1/4 SW 1/4 SW 1/4 SE 1/4</b>		Sec. <b>4</b>	Twp <b>18N</b>
Ft FSL of Qtr Sec <b>330'</b>		Ft FWL of Qtr Sec <b>330'</b>	
Current Well Name/Number <b>FAUST #1</b>		County <b>LOGAN</b>	
Original Well Name/Number		Rge. <b>2W</b>	
Unit Name (if applicable)			


2310'									
1650'									
990'									
330'									
2310'									
1650'									
990'									
330'								X	


5280 ft  
 Locate Well On Grid Above

Well Class:  OIL  GAS  DRY

Producing formation(s)

The effective date of transfer of this well, for the purposes of Commission records, is the date that the transfer is approved by the Commission.

<b>CURRENT OPERATOR</b>			OCC No. <b>11391</b>
Name <b>E. N. SMITH III, ENERGY CORP.</b>			
Address <b>P. O. DRAWER V</b>			
City <b>MARSHALL</b>	State <b>TX</b>	Zip <b>75671-0500</b>	
Phone No. <b>(903) 935-5232</b>	FAX No./E-mail <b>(903) 935-2881</b>		
I verify that I am the legal operator of record with authority to transfer operatorship of this well.			
<i>E N Smith</i>			
Signature			
<b>E. N. SMITH, III</b>			
Name & Title (Typed or Printed)			
Signed and sworn to before me this <u>11<sup>th</sup></u> day of <u>February</u> , <u>2015</u> .			
			
My commission expires: <u>2-16-2015</u>			

<b>NEW OPERATOR</b>			OCC No. <b>11391</b>
Name <b>SMITH RESOURCES, INC.</b>			
Address <b>P. O. DRAWER V</b>			
City <b>MARSHALL</b>	State <b>TX</b>	Zip <b>75671-0500</b>	
Phone No. <b>(903) 935-5232</b>	FAX No./E-mail <b>(903) 935-2881</b>		
I verify that I am the legal operator of record with authority to transfer operatorship of this well.			
<i>E N Smith</i>			
Signature			
<b>E. N. SMITH, III</b>			
Name & Title (Typed or Printed)			
Signed and sworn to before me this <u>11<sup>th</sup></u> day of <u>February</u> , <u>2015</u> .			
			
My commission expires: <u>2-16-2016</u>			

I verify under oath that I have exercised due diligence in attempting to locate the current operator of record according to OCC records, who has abandoned the above well/lease and cannot be located to obtain signature.

I have attached a copy of the certified recorded assignment of lease.

\* APPROVED COPY AVAILABLE ON OCC WEBSITE. \*

Signature \_\_\_\_\_

Signed and sworn to before me this \_\_\_\_\_ day of \_\_\_\_\_, \_\_\_\_\_.

My commission expires: \_\_\_\_\_

Notary Public **FEB 18 2015**

**FOR OCC USE ONLY**

**WELL RECORDS  
 APPROVED**

Surety Dept.  Approved  Rejected Date FEB 18 2015 Well Records Dept.  Approved  Rejected Date \_\_\_\_\_

NOTE: By processing this Form 1073, the Oklahoma Corporation Commission has approved the contents thereof as to form only. Oklahoma Corporation Commission does not warrant that the facts provided by the operator are true. Form is not approved until approved by Well Records.

OK on 1002A's  
 → Tax confirmed w/ George Anne