# Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35007256560000 Completion Report Spud Date: January 24, 2014

OTC Prod. Unit No.: Drilling Finished Date: February 10, 2014

1st Prod Date: March 19, 2014

Completion Date: March 18, 2014

Drill Type: HORIZONTAL HOLE

Well Name: HARRISON 1-30H Purchaser/Measurer:

Location: BEAVER 19 2N 20E CM

S2 S2 SE

280 FSL 1320 FEL of 1/4 SEC

Derrick Elevation: 2709 Ground Elevation: 2693

Operator: UNIT PETROLEUM COMPANY 16711

PO BOX 702500

7130 S LEWIS AVE STE 1000 TULSA, OK 74170-2500

	Completion Type					
Х	Single Zone					
	Multiple Zone					
	Commingled					

Location Exception
Order No
620866

Increased Density
Order No
There are no Increased Density records to display.

First Sales Date:

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9 5/8	36	J-55	1984		605	SURFACE	
INTERMEDIATE	7	26	I-80	5966		310	3127	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	11.6	I-80	4714	0	0	5791	10505

Total Depth: 10505

Packer					
Depth	Brand & Type				
There are no Packer records to display.					

Plug					
Depth Plug Type					
There are no Plug records to display.					

April 08, 2014 1 of 3

				Initial Tes	t Data					
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Mar 19, 2014	MARMATON	90	40	85	944	439	PUMPING			

#### Completion and Test Data by Producing Formation

Formation Name: MARMATON

Code: 404MRMN

Class: OIL

Spacing Orders					
Order No	Unit Size				
620246	640				

Perforated Intervals				
From	То			
6208	10309			

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments
481,820# PROP 33,313 BBLS SW

Formation	Тор
TORONTO	4668
LANSING	4754
KC/CHECKERBOARD	5517
MARMATON	5926

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

## Other Remarks

LINER - NOT CEMENTED

PERF INTERVALS - 12 STAGES

ISIP - VACUUM

FORMATIONS - TORONTO - 4642 TVD; LANSING - 4728 TVD; KC/CHECKERBOARD - 5473 TVD; MARMATON - 5716 TVD. IRREGULAR SECTION. OCC: FLE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED. OPEN HOLE COMPLETION FROM 5966' TO TD OF 10505'.

April 08, 2014 2 of 3

### **Lateral Holes**

Sec: 30 TWP: 2N RGE: 20E County: BEAVER Meridian: CM

C S2 S2 SE

330 FSL 1320 FEL of 1/4 SEC

Depth of Deviation: 5075 Radius of Turn: 674 Direction: 187 Total Length: 4579

Measured Total Depth: 10505 True Vertical Depth: 5774 End Pt. Location From Release, Unit or Property Line: 330

# FOR COMMISSION USE ONLY

1123688

Status: Accepted

April 08, 2014 3 of 3