Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

API No.: 35103245830000

OTC Prod. Unit No.: 103-201520

Completion Report

Spud Date: September 27, 2013

Drilling Finished Date: October 11, 2013 1st Prod Date: April 03, 2014 Completion Date: April 03, 2014

Purchaser/Measurer:

First Sales Date:

Drill Type: HORIZONTAL HOLE

Well Name: BOLAY 29-21N-1E 1WH

Location: NOBLE 19 21N 1E SW SE SE SE 310 FSL 430 FEL of 1/4 SEC Derrick Elevation: 1075 Ground Elevation: 1052

Operator: DEVON ENERGY PRODUCTION CO LP 20751

333 W SHERIDAN AVE DEC 34.428 OKLAHOMA CITY, OK 73102-5010

	Completion Type		Location Exception]	Increased Density			
Х	Single Zone		Order No		Order No			
	Multiple Zone		617281		There are no Increased Density records to display.			
	Commingled	'						

Casing and Cement Туре Size Weight Grade Feet PSI SAX Top of CMT CONDUCTOR 16 75# J-55 8 SURFACE 65 SURFACE SURFACE 9-5/8 36# J-55 495 200 INTERMEDIATE 7 29# L-80 5570 380 5405 Liner Туре Size Weight Grade Length PSI SAX **Top Depth Bottom Depth** LINER 4-1/2 11.60# L-80 5456 0 490 5405 10861

Total Depth: 10861

Pac	ker	Plug			
Depth	Brand & Type	Depth	Plug Type		
There are no Packe	r records to display.	10774	CEMENT		

Initial Test Data												
Test Date	Test Date Formation		Oil BBL/Day	Oil-Gra (AP		as 7/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Apr 09, 2014	WOODFORD		294		2	53	861	3130	PUMPING		25/64	
Completion and Test Data by Producing Formation												
Formation Name: WOODFORD					Code: 319WDFD Class: OIL							
		Perforated Intervals										
Order No Unit Size			nit Size		From			То				
616802 640			640			5620)	10724				
Acid Volumes						Fracture Treatments						
625 BBLS. 15 STAGES					3125637# 30/50							
					140700 BBLS. FLUID							
Formation Top				ор		w	/ere open hole l	ogs run? No				
WOODFORD					4947 Date last log run:							
						W	Were unusual drilling circumstances encountered? No					

Explanation:

Other Remarks

IRREGULAR SECTION.

OCC: FLE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED.

 Lateral Holes

 Sec: 29 TWP: 21N RGE: 1E County: NOBLE

 SE
 SE

 SW
 SW

 50 FSL
 1153 FWL of 1/4 SEC

 Depth of Deviation: 4315 Radius of Turn: 769 Direction: 159 Total Length: 5777

 Measured Total Depth: 10861 True Vertical Depth: 5081 End Pt. Location From Release, Unit or Property Line: 50

FOR COMMISSION USE ONLY

Status: Accepted

May 09, 2014

1124130