

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35085205620002

Completion Report

Spud Date: September 23, 1981

OTC Prod. Unit No.: 085-22937

Drilling Finished Date: January 15, 1982

Amended

1st Prod Date: January 24, 1982

Amend Reason: PLUG AND ABANDONED

Completion Date: January 25, 1982

Recomplete Date: October 24, 2017

Drill Type: STRAIGHT HOLE

Well Name: E L SADLER (EDNA SADLER UNIT 2) 2

Purchaser/Measurer:

Location: LOVE 13 7S 2E
SE NW SE NE
952 FSL 1835 FWL of 1/4 SEC
Derrick Elevation: 0 Ground Elevation: 795

First Sales Date:

Operator: XTO ENERGY INC 21003

810 HOUSTON ST
FORT WORTH, TX 76102-6203

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
There are no Location Exception records to display.	

Increased Density	
Order No	
There are no Increased Density records to display.	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	24	J-55	517		400	SURFACE
PRODUCTION	5 1/2	17	N-80	9065		1000	

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 9066

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Oct 24, 2017	DEESE									

Completion and Test Data by Producing Formation

Formation Name: DEESE

Code: 404DEESS

Class: PLUG AND ABANDON

Spacing Orders

Order No	Unit Size
24541	40

Perforated Intervals

From	To
5218	5476

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments

There are no Fracture Treatments records to display.

Formation	Top
------------------	------------

Were open hole logs run? No
Date last log run:

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks

IRREGULAR SECTION

FOR COMMISSION USE ONLY

Status: Accepted

1138053