Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35007255280000 Completion Report Spud Date: August 18, 2012

OTC Prod. Unit No.: 0072089430000 Drilling Finished Date: September 13, 2012

1st Prod Date: October 16, 2012

Completion Date: November 15, 2012

Drill Type: HORIZONTAL HOLE

Well Name: LAMASTER #1H-23 Purchaser/Measurer:

Location: BEAVER 26 1N 20E CM N2 N2 NW NW

300 FNL 660 FWL of 1/4 SEC

Derrick Elevation: 0 Ground Elevation: 2878

Operator: CHAPARRAL ENERGY LLC 16896

701 CEDAR LAKE BLVD

OKLAHOMA CITY, OK 73114-7800

	Completion Type					
Х	Single Zone					
	Multiple Zone					
	Commingled					

Location Exception					
	Order No				
	597641				
	606293				
	000293				

Increased Density
Order No
There are no Increased Density records to display.

First Sales Date:

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9 5/8	36	K55	1502		775	SURFACE	
INTERMEDIATE	7	26	P110	6722		290	4555	

Liner								
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4 1/2	11.6	P110	4797	0	0	6628	11425

Total Depth: 11448

Packer					
Depth Brand & Type					
There are no Packer records to display.					

Plug						
Depth Plug Type						
There are no Plug records to display.						

January 31, 2013 1 of 2

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Oct 16, 2012	MARMOTON	741	38.6	354	478	1198	PUMPING		N/A	

Completion and Test Data by Producing Formation

Formation Name: MARMOTON

Code: 404MRMN

Class: OIL

Spacing Orders						
Order No	Unit Size					
596954	640					

Perforated Intervals

From To

There are no Perf. Intervals records to display.

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments					
2,278,000 GAL 2% KCL SLICK WATER;					
1,577,600# 40/7					

Formation	Тор
MARMATON	6620

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

PERFORATION INTERVALS SHOWN ABOVE REPRESENTS OPEN HOLE COMPLETION FROM 6722' TO 11425'. IRREGULAR SECTION.

Lateral Holes

Sec: 23 TWP: 1N RGE: 20E County: BEAVER Meridian: CM

SW NE NW NW

344 FNL 706 FWL of 1/4 SEC

Depth of Deviation: 5445 Radius of Turn: 1674 Direction: 349 Total Length: 4329

Measured Total Depth: 11448 True Vertical Depth: 6252 End Pt. Location From Release, Unit or Property Line: 344

FOR COMMISSION USE ONLY

1117313

Status: Accepted

January 31, 2013 2 of 2