

PLUGGING RECORD

OAC 165:10-1-10

WELL INFORMATION

Plug Date: December 18, 2012

API No: 35125053230001

Well #: 1-23

Well Name: MS. AHSOKA (HUBBARD 1)

Operator: XANADU EXPLORATION COMPANY

Operator #: 19754

Section: 23

Township: 9N

Range: 2E

Meridian: IM

C 1/4:

NE 1/4:

NE 1/4:

NW 1/4:

Total Depth: 5379

Base of Treatable: Water: 390

Well Classification:

CONTACT INFORMATION

Contact Name: Larry D Sweet

Telephone: 2394951928

Address 1: 320 S BOSTON AVE STE 2000

Address 2:

City: TULSA

State: OK

Zipcode: 74103-4709

Country: US

Email Address:

Fax:

PIPE RECORDS

PERFORATION DEPTHS

String Name	Size	Run	Pulled
SURFACE	10.75	288	0

From Depth	To Depth
------------	----------

PLUGS

Plug Type	Hole Size	Depth	No. Sacks of Cement	Slurry Volume	Calculated TOC	Top of Plug
CEM	9.875	443	285	34	3	3

Remarks: UNSUCCESSFUL RE-ENTRY

Reason For Plugging: UNSUCCESSFUL RE-ENTRY

CEMENTER CERTIFICATION INFORMATION

Name:

Title:

Company Name: ROADRONNER WELL SERVICE LLC

Permit No: 868

Address 1:

Address 2:

City:

State:

Zipcode:

Phone: (918) 584-3802

I declare that I have knowledge of the contents of this report and am authorized by my organization to make this report, which was prepared by me or under my supervision and direction with the data and facts stated herein to be true, correct and complete to the best of my knowledge and belief.

Electronic Signature: XANADU EXPLORATION COMPANY