Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

Completion Report API No.: 35129238730000 Spud Date: October 04, 2013

OTC Prod. Unit No.: 129-212002 Drilling Finished Date: November 14, 2013

1st Prod Date: December 26, 2013

Completion Date: December 26, 2013

HORIZONTAL HOLE Drill Type:

Well Name: MAXON 4-13H Purchaser/Measurer:

ROGER MILLS 24 14N 24W NE NW NE NE Location:

200 FNL 850 FEL of 1/4 SEC

Latitude: -99.697772 Longitude: 35.681604 Derrick Elevation: 0 Ground Elevation: 2145

SAMSON RESOURCES COMPANY 5415 Operator:

2 W 2ND ST

TULSA, OK 74103-3103

Completion Type						
Х	Single Zone					
	Multiple Zone					
	Commingled					

Location Exception			
Order No			
607519			

Increased Density
Order No
616662

First Sales Date:

Casing and Cement									
Type Size Weight Grade Feet PSI SAX Top of C						Top of CMT			
SURFACE	9 5/8	40.0	J-55	965		480	SURFACE		
INTERMEDIATE	7	26	P-110	11058		450	3200		
PRODUCTION	4 1/2	13.50	P-110	15091		1380	7714		

Liner									
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth	
There are no Liner records to display.									

Total Depth: 15461

Packer					
Depth Brand & Type					
There are no Packer records to display.					

Plug						
Depth Plug Type						
There are no Plug records to display.						

January 29, 2014 1 of 2

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Jan 04, 2014	MARMATON	690.5		4936	7148	1353	FLOWING	4868	30/64	1400

Completion and Test Data by Producing Formation

Formation Name: MARMATON

Code: 404MRMN

Class: OIL

Spacing Orders						
Order No	Unit Size					
603998	640					

Perforated Intervals					
From To					
11624	15088				

Acid Volumes

25,000 GALS 7 1/2% ACID

Fracture Treatments					
FRAC'D W/2,034,782 #'S PROPPANT AND 55,151 BBLS					
ELLID					

Formation	Тор
TONKAWA	8890
CLEVELAND	10470
MARMATON	11240

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

A DV TOOL WAS USED. SETTING DEPTH OF 6,712' WITH 325 SACKS CEMENT. IRREGULAR SECTION. OCC: FLE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED.

Lateral Holes

Sec: 13 TWP: 14N RGE: 24W County: ROGER MILLS

SE SW NE NE

1073 FNL 869 FEL of 1/4 SEC

Depth of Deviation: 10719 Radius of Turn: 590 Direction: 360 Total Length: 3850

Measured Total Depth: 15461 True Vertical Depth: 11234 End Pt. Location From Release, Unit or Property Line: 869

FOR COMMISSION USE ONLY

1122499

Status: Accepted

January 29, 2014 2 of 2