

Oklahoma Corporation Commission
 Oil & Gas Conservation Division
 Post Office Box 52000
 Oklahoma City, Oklahoma 73152-2000
 Rule 165: 10-3-25

Form 1002A

API No.: 35103246030000

Completion Report

Spud Date: November 23, 2013

OTC Prod. Unit No.: 103-213004

Drilling Finished Date: December 06, 2013

1st Prod Date: March 10, 2014

Completion Date: March 10, 2014

Drill Type: HORIZONTAL HOLE

Well Name: WOSMEK 23-20N-1W 1WH

Purchaser/Measurer:

Location: NOBLE 23 20N 1W
 W2 NE NW NW
 330 FNL 750 FWL of 1/4 SEC
 Derrick Elevation: 1118 Ground Elevation: 1088

First Sales Date:

Operator: DEVON ENERGY PRODUCTION CO LP 20751

333 W SHERIDAN AVE DEC 34.428
 OKLAHOMA CITY, OK 73102-5010

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
620715

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	16	84#	J-55	70		11	SURFACE
SURFACE	9-5/8	36#	J-55	500		305	SURFACE
INTERMEDIATE	7	26#	RYH110	5762		410	3352

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4-1/2	11.60#	RYH110	4531	0	465	5513	10044

Total Depth: 10047

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
9962	CEMENT

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Mar 24, 2014	WOODFORD	231		342	1481	1682	PUMPING		64/64	

Completion and Test Data by Producing Formation										
Formation Name: WOODFORD			Code: 319WDFD			Class: OIL				
Spacing Orders				Perforated Intervals						
Order No		Unit Size		From			To			
619523		640		5803			9874			
Acid Volumes				Fracture Treatments						
506 BBLs. 13 STAGES				86833# 100 MESH						
				2531302# 30/50						
				153871 BBLs. FLUID						

Formation	Top
WOODFORD	5642

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
IRREGULAR SECTION. OCC: FILE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED.

Lateral Holes

Sec: 23 TWP: 20N RGE: 1W County: NOBLE

SE SW SW SW

50 FSL 653 FWL of 1/4 SEC

Depth of Deviation: 4402 Radius of Turn: 828 Direction: 181 Total Length: 4817

Measured Total Depth: 10047 True Vertical Depth: 5231 End Pt. Location From Release, Unit or Property Line: 50

FOR COMMISSION USE ONLY

1123707

Status: Accepted