

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35045234300000

Completion Report

Spud Date: February 03, 2014

OTC Prod. Unit No.:

Drilling Finished Date: March 06, 2014

1st Prod Date: May 08, 2014

Completion Date: May 05, 2014

Drill Type: HORIZONTAL HOLE

Well Name: SHREWDER 4-18H

Purchaser/Measurer: DCP

Location: ELLIS 19 18N 23W
N2 N2 NE NE
100 FNL 660 FEL of 1/4 SEC
Derrick Elevation: 0 Ground Elevation: 2464

First Sales Date: 5/8/2014

Operator: PPP PETROLEUM LP 23356

2101 CEDAR SPRINGS RD STE 1800
DALLAS , TX 75201-1585

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
622202	

Increased Density	
Order No	
622338	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	20	52.73	X-52	100		20	SURFACE
SURFACE	9 5/8	36	J-55	1516		595	SURFACE
INTERMEDIATE	7	23	L-80	8692		310	2598
PRODUCTION	4 1/2	11.6	P-110	13674		405	8060

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 13676

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
May 10, 2014	CLEVELAND	153	40	320	2092	1078	FLOWING		64/64	220

Completion and Test Data by Producing Formation										
Formation Name: CLEVELAND			Code: 405CLVD			Class: OIL				
Spacing Orders				Perforated Intervals						
Order No		Unit Size		From			To			
346643		640		9580			13670			
Acid Volumes				Fracture Treatments						
There are no Acid Volume records to display.				3560100 40/70 WHITE SAND, 70441 BBLS FRESH WATER						

Formation	Top
CLEVELAND	9200

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
OCC: FLE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED. IRREGULAR SECTION.

Lateral Holes
<p>Sec: 18 TWP: 18N RGE: 23W County: ELLIS</p> <p>C SW NW NE</p> <p>990 FNL 330 FWL of 1/4 SEC</p> <p>Depth of Deviation: 8351 Radius of Turn: 773 Direction: 360 Total Length: 4620</p> <p>Measured Total Depth: 13676 True Vertical Depth: 9293 End Pt. Location From Release, Unit or Property Line: 990</p>

FOR COMMISSION USE ONLY	
Status: Accepted	1124233