#### OKLAHOMA CORPORATION COMMISSION **Oil & Gas Conservation Division** Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

# **PLUGGING RECORD**

OAC 165:10-1-10

Well Name: SHOE MOUNTAIN

### WELL INFORMATION

API No: 3512123098

Well #:	1-2	23					

**Operator: XANADU EXPLORATION COMPANY** 

Section: 23	Township: 7N	Range: 18E	Meridian: Indian
S2 1/4:	N2 1/4:	SW4 1/4:	SW4 1/4:
Total Depth: 3350	Base of Tre	eatable: Water: 400	Well Classification: GAS

# **CONTACT INFORMATION**

Contact Name: Larry D S	Telep	<b>Telephone:</b> 2394951928		
Address 1: 320 S BC	OSTON AVE STE 200	00 Addre	ess 2:	
City: TULSA	State: OK	Zipcode: 74103-4709	Country: US	
Email Address:			Fax:	

Fax:

**Operator #: 19754** 

### **PIPE RECORDS**

String Name	Size	Run	Pulled
SURFACE	8.625	660	0
PRODUCTION	4.5	3332	625

#### PLUGS

Plug Type	Hole Size	Depth	No. Sacks of Cement	Slurry Volume	Calculated TOC	Top of Plug
CIBP	4.5	2940	2	2	2920	2920
CEM	8.625	760	80	88	500	500
CEM	8.625	120	40	44	4	4

Remarks: WITINESS MR. RANDY WILLIAMSON OCC. FILLED WELL WITH MUD BEFORE PLUGGING.

Reason For Plugging: DRY

# **CEMENTER CERTIFICATION INFORMATION**

Name: Title:				
Company Name: SHARP WEL	L CEMENTING	Permit No: 589		
Address 1:		Address 2	<b>2:</b> P.O. Box 98	
City: HUNTINGTON	State: AR	<b>Zipcode:</b> 72940	Phone: (479) 996-2799	

I declare that I have knowledge of the contents of this report and am authorized by my organization to make this report, which was prepared by me or under my supervision and direction with the data and facts stated herein to be true, correct and complete to the best of my knowledge and belief.

# Electronic Signature: XANADU EXPLORATION COMPANY

# **PERFORATION DEPTHS**

From Depth	To Depth
2990	3198
2990	5190

Plug Date: September 30, 2014

Form	1003