

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35105412070000

Completion Report

Spud Date: December 05, 2014

OTC Prod. Unit No.:

Drilling Finished Date: December 09, 2014

1st Prod Date: February 22, 2015

Completion Date: January 29, 2015

Drill Type: STRAIGHT HOLE

Well Name: PHYLLIS 1

Purchaser/Measurer:

Location: NOWATA 13 27N 15E
SE SW SE SE
165 FSL 825 FEL of 1/4 SEC
Latitude: -95.6505 Longitude: 36.815472
Derrick Elevation: 733 Ground Elevation: 728

First Sales Date:

Operator: MARJO OPERATING COMPANY INC 19301
PO BOX 729
427 S BOSTON AVE STE 240
TULSA, OK 74101-0729

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	24	J55	97		50	SURFACE
PRODUCTION	5 1/2	15.5	J55	1132		190	18

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 1170

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Feb 24, 2015	BARTLESVILLE	7				5	PUMPING			

Completion and Test Data by Producing Formation										
Formation Name: BARTLESVILLE			Code: 404BRVL			Class: OIL				
Spacing Orders				Perforated Intervals						
Order No		Unit Size		From			To			
There are no Spacing Order records to display.				869			904			
Acid Volumes				Fracture Treatments						
500 GALS 15% HCL				270 BBLS GEL W/9200 LBS SAND						

Formation	Top
OSWEGO	512
VERDIGRIS	590
SKINNER	614
BARTLESVILLE	849
MISSISSIPPI CHAT	1108
MISSISSIPPI LIME	1140

Were open hole logs run? Yes
Date last log run: December 09, 2014

Were unusual drilling circumstances encountered? No
Explanation:

Other Remarks
There are no Other Remarks.

FOR COMMISSION USE ONLY	
Status: Accepted	1128007