Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35031201050001 **Completion Report** Spud Date: November 11, 1967

Drilling Finished Date: November 26, 1967 OTC Prod. Unit No.:

1st Prod Date: April 15, 1968

Amended Completion Date: April 15, 1968 Amend Reason: RETURN TO OIL PRODUCTION

Recomplete Date: May 16, 2016

Drill Type: STRAIGHT HOLE

Well Name: CONTINENTAL B-1 Purchaser/Measurer:

COMANCHE 3 3N 10W Location: First Sales Date:

SW SW NE SE 1550 FSL 1550 FWL of 1/4 SEC

Latitude: 34.75792 Longitude: -98.23234 Derrick Elevation: 0 Ground Elevation: 0

TURNER R L OIL COMPANY LLC 22280 Operator:

> 1503 W BOIS D ARC AVE DUNCAN, OK 73533-4826

Completion Type				
Х	Single Zone			
	Multiple Zone			
	Commingled			

Location Exception
Order No
There are no Location Exception records to display.

Increased Density					
Order No					
There are no Increased Density records to display.					

Casing and Cement								
Type Size Weight Grade Feet PSI SAX Top of CMT								
PRODUCTION 2 7/8 6 J-55 1206 255 SURFACE								

				Liner						
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth		
	There are no Liner records to display.									

Total Depth: 1206

Packer				
Depth	Brand & Type			
There are no Packer records to display.				

Plug				
Depth Plug Type				
There are no Plug records to display.				

June 08, 2016 1 of 2

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
May 16, 2016	FORTUNA	0.75	34.4			5				

Completion and Test Data by Producing Formation

Formation Name: FORTUNA

Code: 451FRTN

Class: OIL

Spacing Orders				
Order No	Unit Size			
There are no Spacing Order records to display.				

Perforated Intervals				
From To				
1166	1176			

Acid Volumes

There are no Acid Volume records to display.

Fracture	Treatments
----------	------------

There are no Fracture Treatments records to display.

Formation	Тор
RED BEDS	0
WATER SAND	50
SHALE AND SANDY SHALE STRIKE	60
BROKEN WATER SAND	690
SHALE	751
SHALEY WATER SAND	838
SHALE	846
BROKEN WATER SAND	902
LIME	940
SHALE	944
OIL SAND	1163
SHALE	1176

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

AMENDED 1002A REQUESTED BY CORPORATION COMMISSION

FOR COMMISSION USE ONLY

1133629

Status: Accepted

June 08, 2016 2 of 2

NAME (PRINT OR TYPE)

73533

ZIP

OK

STATE

Duncan

CITY

SIGNATURE

1503 West Bois D Arc

ADDRESS

PHONE NUMBER

DATE

rlturner1967@sbcglobal.net

EMAIL ADDRESS


PLEASE TYPE OR USE BLACK INK ONLY FORMATION RECORD

Give formation names and tops, if available, or descriptions and thickness of formations drilled through. Show intervals cored or drillstem tested.

diffied through. Show intervals cored or diffistern tested.	
NAMES OF FORMATIONS	TOP
Red Bed	0 - 50
Water Sand	50 - 60
Shale & Sandy Shale Strike	60 - 690
Broken Water Sand	690 - 751
Shale`	751 - 838
Shaley Water Sand	838 - 846
Shale	846 - 902
Broken Water Sand	902 - 940
Lime	940 - 944
Shale	944 - 1163
Oil Sand	1163 - 1176
Shale	1176 - 1206
TD	1,206

LEASE NAME _	Conti	nenta	l 	w	ELL NO	4
		FOR	COMMIS	SION USE ONL	Y	
ITD on file APPROVED	YES	□NO	2) Reject	Codes		
Were open hole lo Date Last log was Was CO ₂ encount	гиn	yes	no	at what depth	s?	
- Was H₂S encounte	ered?	yes	no	at what depth		

Other remarks:	Amended 1002 A requested by Corporation Commission



If more than three drainholes are proposed, attach a separate sheet indicating the necessary information.

Direction must be stated in degrees azimuth. Please note, the horizontal drainhole and its end point must be located within the boundaries of the lease or spacing unit.

Directional surveys are required for all drainholes and directional wells.

		640 /	Acres			
	Ì					
	+		-		ļ	
	İ					
	Ì					
	1					
	<u> </u>					
				L		
					L	

BOTTOM HOLE LOCATION FOR DIRECTIONAL HOLE

SEC	TWP	RGE	COUNTY	,			
Spot Loc	ation 1/4	1/4	1/4	1/4 Fee	t From 1/4 Sec Lines	FSL	FWL
Measure	d Total Depth	True	Vertical Depth		. From Lease, Unit, or Pr	operty Line:	

BOTTOM HOLE LOCATION FOR HORIZONTAL HOLE: (LATERALS)

LATERAL #1

SEC TWP	RGE	C	OUNTY			
Spot Location	1/4	1/4	1/-	Feet From 1/4 Sec Lines	FSL	FWL
Depth of Deviation		Radius of Turn		Direction	Total Length	
Measured Total Depth	1	True Vertical Dept	h	BHL From Lease, Unit, or Pr	operty Line:	

LATERAL #2

SEC	TWP	RGE		COUNTY			
Spot Loc	ation 1/4	1/4	1/4	1/4	Feet From 1/4 Sec Lines	FSL	FWL
Depth of			Radius of Turn	-	Direction	Total	
Deviation	·		True Vertical Des	-th	BHL From Lease, Unit, or Pr	Length	
ivieasure	d Total Depth		True Vertical Dep	วเท	DOL From Lease, Onk, or Fr	operty time.	

SEC	TWP	RGE		COUNTY			
Spot Loc	cation				Feet From 1/4 Sec Lines	FSL	FWL
	1/4	1/4	1/4	1/4			
Depth of	•		Radius of Turn		Direction	Total	1
Deviation	n					Length	
Measure	d Total Depth		True Vertical De	pth	BHL From Lease, Unit, or Pre	operty Line:	