Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: 04521785000000 Drilling Finished Date: July 01, 2016

1st Prod Date: August 04, 2016

Completion Date: July 03, 2016

First Sales Date: 08-14-2016

Drill Type: HORIZONTAL HOLE

Well Name: BAY 15 6H Purchaser/Measurer: ETC FIELD SERVICES

Location: ELLIS 10 20N 26W

NE SW SE SW

656 FSL 1760 FWL of 1/4 SEC

Derrick Elevation: 2450 Ground Elevation: 2431

Operator: JONES ENERGY LLC 21043

807 LAS CIMAS PKWY STE 350 AUSTIN, TX 78746-6193

Completion Type							
Χ	Single Zone						
	Multiple Zone						
	Commingled						

Location Exception			
Order No			
654079			
655447			

Increased Density
Order No
656411

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9.625	36	J55	803		505	SURFACE	
INTERMEDIATE	7	26	P110	8886	_	405	2553	

Liner									
Type Size Weight Grade Length PSI SAX Top Depth Bottom Depth								Bottom Depth	
LINER	4.5	14	P110	4664	0	0	8679	13343	

Total Depth: 13345

Packer				
Depth	Brand & Type			
There are no Packer records to display.				

Plug			
Depth	Plug Type		
There are no Plug	records to display.		

November 07, 2016 1 of 2

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Aug 17, 2016	CLEVELAND	148	44.7	23	155	168	FLOWING	900	1-64	175

Completion and Test Data by Producing Formation

Formation Name: CLEVELAND

Code: 405CLVD

Class: OIL

Spacing Orders					
Order No	Unit Size				
555427	640				
555427	640				

Perforated Intervals				
From	То			
8907	13324			

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments	
56039 BBLS FLUID 2486980 LBS PROPPANT	

Formation	Тор
CLEVELAND	8175

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC: FLE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED. IRREGULAR SECTION.

Lateral Holes

Sec: 15 TWP: 20N RGE: 26W County: ELLIS

NW SW SE SW

382 FSL 1628 FWL of 1/4 SEC

Depth of Deviation: 7247 Radius of Turn: 650 Direction: 180 Total Length: 4470

Measured Total Depth: 13345 True Vertical Depth: 8192 End Pt. Location From Release, Unit or Property Line: 382

FOR COMMISSION USE ONLY

1134764

Status: Accepted

November 07, 2016 2 of 2

