Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

Completion Report API No.: 35045236130000 Spud Date: June 19, 2016

OTC Prod. Unit No.: 04521784900000 Drilling Finished Date: June 29, 2016

1st Prod Date: August 02, 2016

Completion Date: July 02, 2016

First Sales Date: 08-02-2016

HORIZONTAL HOLE Drill Type:

Well Name: BAY 15 5H Purchaser/Measurer: ETC FIELD SERVICES

Location: ELLIS 10 20N 26W

SW SE SW SE 295 FSL 1875 FEL of 1/4 SEC

Derrick Elevation: 2458 Ground Elevation: 2439

JONES ENERGY LLC 21043 Operator:

> 807 LAS CIMAS PKWY STE 350 AUSTIN, TX 78746-6193

Completion Type							
Χ	Single Zone						
	Multiple Zone						
	Commingled						

Location Exception			
Order No			
654078			
654809			

Increased Density
Order No
656411

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9.265	36	J55	845		505	SURFACE	
INTERMEDIATE	7	26	P110	8516	_	405	3742	

Liner									
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth	
LINER	4.5	14	P110	6186	0	0	6882	13068	

Total Depth: 13188

Packer				
Depth	Brand & Type			
There are no Packer records to display.				

Plug			
Depth	Plug Type		
There are no Plug	records to display.		

November 07, 2016 1 of 2

	Initial Test Data									
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Aug 04, 2016	CLEVELAND	56	44.5	221	3946	140	FLOWING	760	1-64	150

Completion and Test Data by Producing Formation

Formation Name: CLEVELAND

Code: 405CLVD

Class: OIL

Spacing Orders					
Order No	Unit Size				
555427	640				

Perforated Intervals				
From	То			
8629	13158			

Acid Volumes

There are no Acid Volume records to display.

Fracture Treatments	
58185 BBLS FLUID 2459576 LBS PROPPANT	

Formation	Тор
CLEVELAND	8183

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

OCC: FLE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED. IRREGULAR SECTION.

Lateral Holes

Sec: 15 TWP: 20N RGE: 26W County: ELLIS

NW SE SW SE

334 FSL 1766 FEL of 1/4 SEC

Depth of Deviation: 7200 Radius of Turn: 650 Direction: 180 Total Length: 4609

Measured Total Depth: 13188 True Vertical Depth: 8214 End Pt. Location From Release, Unit or Property Line: 334

FOR COMMISSION USE ONLY

1134740

Status: Accepted

November 07, 2016 2 of 2

