

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35125239110000

Completion Report

Spud Date: August 23, 2016

OTC Prod. Unit No.:

Drilling Finished Date: August 28, 2016

1st Prod Date: October 14, 2016

Completion Date: September 12, 2016

Drill Type: STRAIGHT HOLE

Min Gas Allowable: Yes

Well Name: HAZELL 1

Purchaser/Measurer:

Location: POTTAWATOMIE 15 7N 3E
SE NW SW NE
1800 FNL 2050 FEL of 1/4 SEC
Latitude: 35.082304454 Longitude: -96.973376068
Derrick Elevation: 1016 Ground Elevation: 1003

First Sales Date:

Operator: MARJO OPERATING MID-CONTINENT LLC 23610
PO BOX 729
427 S BOSTON AVE STE 240
TULSA, OK 74101-0729

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
657618

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8 5/8	24	J55	480		305	SURFACE
PRODUCTION	5 1/2	15.5	J55	4590		125	3994

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 4602

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Oct 16, 2016	HUNTON	15		115	7667		PUMPING	45		

Completion and Test Data by Producing Formation										
Formation Name: HUNTON			Code: 269HNTN			Class: OIL				
Spacing Orders				Perforated Intervals						
Order No	Unit Size			From			To			
643254	640			4440			4464			
Acid Volumes				Fracture Treatments						
2000 GALS 15% ACID				There are no Fracture Treatments records to display.						

Formation	Top
HOGSHOOTER	2958
LAYTON	2990
CHECKERBOARD	3291
EARLSBORO	4198
MISSISSIPPI	4300
WOODFORD	4341
HUNTON FRISCO	4388
HUNTON BOIS D'ARC	4397
HUNTON HARAGAN	4486

Were open hole logs run? Yes

Date last log run: August 29, 2016

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks
There are no Other Remarks.

FOR COMMISSION USE ONLY	
Status: Accepted	1134477