## Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

API No.: 35049247420004 **Completion Report** Spud Date: May 31, 2009

OTC Prod. Unit No.: 049-20250 Drilling Finished Date: July 01, 2009

1st Prod Date: July 22, 2009

**Amended** Completion Date: August 31, 2009 Amend Reason: ADDITIONAL PERFS - DEESE

Recomplete Date: May 18, 2016

**DIRECTIONAL HOLE Drill Type:** 

Location:

Well Name: JC 1-24 Purchaser/Measurer: CIMMARRON GATHERING

GARVIN 19 3N 1W First Sales Date: 08/21/09 W2 NW NW NW

2310 FSL 300 FWL of 1/4 SEC

Latitude: -97.3522171 Longitude: 34.7237756 Derrick Elevation: 948 Ground Elevation: 936

RANKEN ENERGY CORPORATION 17205 Operator:

457 W 18TH ST

EDMOND, OK 73013-3663

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8-5/8"	24#	J-55 ST&C	164		130	SURFACE
PRODUCTION	5-1/2"	17#	J-55 LT&C	5714		507	3350

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 6670

Packer			
Depth	Brand & Type		
There are no Packer records to display.			

Plug				
Depth	Plug Type			
5290	CIBP			

November 18, 2016 1 of 3

				Initial Tes	t Data					
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
May 28, 2016	DEESE1	1	46.79	47	47000	26	PUMPING		·	

#### **Completion and Test Data by Producing Formation**

Formation Name: DEESE1

Code: 404DEES1

Class: GAS

Spacing Orders				
Order No	Unit Size			
189927	40			

Perforated Intervals			
From	То		
5114	5122		

Acid Volumes

2,100 GLNS 7.5% HCL, 1,000 GLNS 15% HCL, 313 BBLS

_			_		
F	raci	III	Troat	tments	

There are no Fracture Treatments records to display.

Formation	Тор
HOGSHOOTER LIME	4698
LAYTON SAND	4778
CHECKERBOARD LIME	5004
DEESE	5032
1ST DEESE	5089
BASE PENN / VIOLA LIME	5137
BROMIDE DENSE LIME	5307
GREEN SHALE MARKER	5413
1ST BROMIDE SAND	5424
2ND BROMIDE SAND	5581
3RD BROMIDE SAND	5732
MCLISH	5950
UPPER MCLISH SAND	6014
BASAL MCLISH SAND	6134
BASAL OIL CREEK SAND	6470

Were open hole logs run? Yes Date last log run: June 30, 2009

Were unusual drilling circumstances encountered? No Explanation:

### Other Remarks

There are no Other Remarks.

November 18, 2016 2 of 3

#### **Bottom Holes**

Sec: 24 TWP: 3N RGE: 2W County: GARVIN

SW NE NE NE

2284 FSL 2243 FWL of 1/4 SEC

Depth of Deviation: 0 Radius of Turn: 0 Direction: 0 Total Length: 0

Measured Total Depth: 6670 True Vertical Depth: 6607 End Pt. Location From Release, Unit or Property Line: 356

# FOR COMMISSION USE ONLY

1134914

Status: Accepted

November 18, 2016 3 of 3