

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35045236100000

Completion Report

Spud Date: June 02, 2016

OTC Prod. Unit No.: 045217852

Drilling Finished Date: June 14, 2016

1st Prod Date: August 04, 2016

Completion Date: June 16, 2016

Drill Type: HORIZONTAL HOLE

Well Name: NEIDENS 10 4H

Purchaser/Measurer:

Location: ELLIS 10 20N 26W
NW NW NW NE
241 FNL 2420 FEL of 1/4 SEC
Latitude: -99.573937 Longitude: 36.134961
Derrick Elevation: 2447 Ground Elevation: 2438

First Sales Date:

Operator: JONES ENERGY LLC 21043

807 LAS CIMAS PKWY STE 350
AUSTIN, TX 78746-6193

Completion Type		Location Exception		Increased Density	
X	Single Zone	Order No		Order No	
	Multiple Zone	646248		646047	
	Commingled				

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	13.375	55	J55	605		685	SURFACE
INTERMEDIATE	7	26	P110	8404		385	8404

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	4.50	13.5	L80	4109	0	0	8460	12569

Total Depth: 12590

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Sep 07, 2016	CLEVELAND	255	44	1060	4157	260	FLOWING	2566	1/64	105

Completion and Test Data by Producing Formation

Formation Name: CLEVELAND

Code: 405CLVD

Class: OIL

Spacing Orders

Order No	Unit Size
566183	640

Perforated Intervals

From	To
There are no Perf. Intervals records to display.	

Acid Volumes

There are no Acid Volume records to display.
--

Fracture Treatments

54071 BBLS OF FLUID, 2,488,580 LBS SAND

Formation	Top
CLEVELAND	8049

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

OCC: FLE ORDER HAS NOT BEEN ISSUED. WE HAVE ACCEPTED OPERATORS DATA AS SUBMITTED. IRREGULAR SECTION.

Lateral Holes

Sec: 10 TWP: 20N RGE: 26W County: ELLIS

SE SE SE SW

198 FSL 2609 FWL of 1/4 SEC

Depth of Deviation: 7286 Radius of Turn: 650 Direction: 180 Total Length: 4186

Measured Total Depth: 12590 True Vertical Depth: 8119 End Pt. Location From Release, Unit or Property Line: 198

FOR COMMISSION USE ONLY

1135714

Status: Accepted