

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35049247130001

Completion Report

Spud Date: August 31, 2008

OTC Prod. Unit No.: 049-124977

Drilling Finished Date: September 13, 2008

Amended

1st Prod Date: November 04, 2008

Amend Reason: RECOMPLETION TO - VIOLA

Completion Date: November 03, 2008

Recomplete Date: April 25, 2017

Drill Type: STRAIGHT HOLE

Well Name: HULSEY 2-8

Purchaser/Measurer:

Location: GARVIN 8 4N 1E
C NE SE NE
990 FSL 2310 FWL of 1/4 SEC
Latitude: 34.835778 Longitude: -97.213972
Derrick Elevation: 1046 Ground Elevation: 1034

First Sales Date:

Operator: RANKEN ENERGY CORPORATION 17205

457 W 18TH ST
EDMOND, OK 73013-3663

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	8-5/8"	23#	ST&C	364		255	SURFACE
PRODUCTION	5-1/2"	15.5#	LT&C	4918		400	3150'

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 5050

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
4650'	CIBP

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Apr 25, 2017	VIOLA	1	38			7	PUMPING			

Completion and Test Data by Producing Formation

Formation Name: VIOLA

Code: 202VIOL

Class: OIL

Spacing Orders

Order No	Unit Size
166480	40

Perforated Intervals

From	To
4503	4520
4578	4591

Acid Volumes

3,350 GLNS 15% HCL -- 80 BBLs. 2% KCL

Fracture Treatments

There are no Fracture Treatments records to display.
--

Formation	Top
HOGSHOOTER LIME	3970
CHECKERBOARD LIME	4236
DEESE	4252
1ST DEESE	4278
2ND DEESE	4370
GIBSON SAND	4453
BASAL PENN / VIOLA LIME	4501
BROMIDE DENSE LIME	4708
GREEN SHALE MARKER	4789
1ST BROMIDE SAND	4808
1ST BROMIDE "C" SAND	4828
1ST BROMIDE "D" SAND	4859
2ND BROMIDE SAND	4952

Were open hole logs run? Yes

Date last log run: September 11, 2008

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1137000

Status: Accepted