

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35137022940001

Completion Report

Spud Date: September 04, 1949

OTC Prod. Unit No.: 137-165030

Drilling Finished Date: September 21, 1949

Amended

1st Prod Date: September 28, 1949

Amend Reason: TEMPORARILY ABANDONED

Completion Date: September 26, 1949

Recomplete Date: April 23, 2018

Drill Type: STRAIGHT HOLE

Well Name: HUMPHREY 4-A

Purchaser/Measurer:

Location: STEPHENS 3 1S 4W
SW NE SW NE
960 FSL 960 FWL of 1/4 SEC
Derrick Elevation: 1011 Ground Elevation: 1003

First Sales Date:

Operator: SAJAC ENERGY COMPANY LLC 19467
PO BOX 207
1032 MAIN PL STE 400
DUNCAN, OK 73534-0207

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
There are no Location Exception records to display.	

Increased Density	
Order No	
There are no Increased Density records to display.	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	10 3/4	33.75	J & L	359		300	SURFACE
PRODUCTION	5 1/2	14	J & L	3972		175	

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 3999

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data										
Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
There are no Initial Data records to display.										

Completion and Test Data by Producing Formation

Formation Name: DEESE

Code: 404DEESS

Class: TA

Spacing Orders

Order No	Unit Size
There are no Spacing Order records to display.	

Perforated Intervals

From	To
3791	3994

Acid Volumes

There are no Acid Volume records to display.
--

Fracture Treatments

There are no Fracture Treatments records to display.
--

Formation	Top
DEESE	3791
DEESE	3972

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1139614

Status: Accepted