

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35137275020000

Completion Report

Spud Date: August 12, 2017

OTC Prod. Unit No.: 137-222954 & 049-222954

Drilling Finished Date: October 10, 2017

1st Prod Date: January 08, 2018

Completion Date: December 31, 2017

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: CELESTA 4R-5-32XH

Purchaser/Measurer: ENABLE MIDSTREAM

Location: STEPHENS 5 2N 4W
SW SW SE SW
250 FSL 1455 FWL of 1/4 SEC
Derrick Elevation: 1204 Ground Elevation: 1179

First Sales Date: 01/08/2017

Operator: CONTINENTAL RESOURCES INC 3186
PO BOX 269000
20 N BROADWAY AVE
OKLAHOMA CITY, OK 73126-9000

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
676625	

Increased Density	
Order No	
666885	
679790	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	13 3/8	55	J-55	1500		373	SURFACE
INTERMEDIATE	9 5/8	40	P-110	13200		855	4943
PRODUCTION	5 1/2	23 & 26	P-110 ICY	24130		4282	11250

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 24130

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Jan 27, 2018	SPRINGER	406	44	623	1534	2967	FLOWING	5100	26/64	

Completion and Test Data by Producing Formation

Formation Name: SPRINGER

Code: 401 SPRG

Class: OIL

Spacing Orders

Order No	Unit Size
672209	MULTIUNIT
131585	640

Perforated Intervals

From	To
14030	23960

Acid Volumes

2691 BBLS 15% HCL ACID

Fracture Treatments

575,711 BBLS OF FLUID & 19,033,153,LBS OF SAND

Formation	Top
SPRINGER	13749

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

APPROVED BASED ON DATA SUBMITTED FINAL ORDER NOT SUBMITTED

Lateral Holes

Sec: 32 TWP: 3N RGE: 4W County: GARVIN

SW NW NE NW

334 FNL 1523 FWL of 1/4 SEC

Depth of Deviation: 13372 Radius of Turn: 398 Direction: 1 Total Length: 10100

Measured Total Depth: 24130 True Vertical Depth: 13494 End Pt. Location From Release, Unit or Property Line: 250

FOR COMMISSION USE ONLY

1138437

Status: Accepted