

Oklahoma Corporation Commission
Oil & Gas Conservation Division
Post Office Box 52000
Oklahoma City, Oklahoma 73152-2000
Rule 165: 10-3-25

Form 1002A

API No.: 35139011270001

Completion Report

Spud Date: August 01, 1945

OTC Prod. Unit No.:

Drilling Finished Date: September 08, 1945

Amended

1st Prod Date: September 18, 1945

Amend Reason: NEW FRACTURE STIMULATION

Completion Date: September 18, 1945

Recomplete Date: November 12, 2018

Drill Type: STRAIGHT HOLE

Well Name: A HELLBUSCH 1

Purchaser/Measurer:

Location: TEXAS 10 4N 14E CM
SW SW SW NE
2500 FNL 2530 FEL of 1/4 SEC
Latitude: 36.82825 Longitude: -101.536944
Derrick Elevation: 3226 Ground Elevation: 0

First Sales Date:

Operator: SCOUT ENERGY MANAGEMENT LLC 23138

4901 LBJ FWY STE 300
DALLAS, TX 75244-6107

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception
Order No
There are no Location Exception records to display.

Increased Density
Order No
There are no Increased Density records to display.

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	10.75	32.75	LW	335		300	SURFACE
PRODUCTION	7	20	SS	2680		1000	600

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
LINER	5.5	14		129	0	0	2651	2780

Total Depth: 2780

Packer	
Depth	Brand & Type
2640	PACKER

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
Nov 12, 2018	GUYMON-HUGOTON			319			FLOWING	1071		

Completion and Test Data by Producing Formation

Formation Name: GUYMON-HUGOTON

Code: 451GYHG

Class: GAS

Spacing Orders

Order No

Unit Size

There are no Spacing Order records to display.

Perforated Intervals

From

To

2680

2780

Acid Volumes

1,000 GALLONS 15% HCL

Fracture Treatments

50,000 POUNDS 16/30 SAND WITH 444 POUNDS WATER, SPEC. GRAVITY 2.65 - 75 QUALITY FOAM

Formation	Top
KRIDER	2700
WLD	2745
HERINGTON	2662
TOWANDA	2809

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

FOR COMMISSION USE ONLY

1141463

Status: Accepted