# Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000 Rule 165: 10-3-25

OTC Prod. Unit No.: 051-225883-0-0000 Drilling Finished Date: January 08, 2019

1st Prod Date: August 08, 2019

Completion Date: July 20, 2019

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: ADAMS 27-34 3XH Purchaser/Measurer: ENABLE

Location: GRADY 27 6N 6W First Sales Date: 8/8/2019

NE NE NW NW

201 FNL 1130 FWL of 1/4 SEC

Latitude: 34.970819 Longitude: -97.825365 Derrick Elevation: 1075 Ground Elevation: 1043

Operator: RED WOLF OPERATING LLC 24373

801 West Covell Rd EDMOND, OK 73003-2179

Completion Type					
Х	Single Zone				
	Multiple Zone				
	Commingled				

Location Exception			
Order No			
706397			

Increased Density			
Order No			
702291			
702292			

Casing and Cement							
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
SURFACE	13.375	68	J-55	1497	891	675	SURFACE
INTERMEDIATE	9.625	40	P-110	12737	1184	1281	6995
PRODUCTION	5.5	23	P-110	24703	6000	2708	10454

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
			There are	no Liner record	ds to displa	ay.		

Total Depth: 24703

Packer				
Depth Brand & Type				
There are no Packer records to display.				

Plug					
Depth Plug Type					
There are no Plug records to display.					

**Initial Test Data** 

January 08, 2020 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Sep 10, 2019	WOODFORD	633	57	8527	13.471	1367	FLOWING	4700	26/64	4227

## **Completion and Test Data by Producing Formation**

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders				
Order No	Unit Size			
666457	640			
669414	640			
706402	MULTIUNIT			

Perforated Intervals				
From To				
14724	24531			

Acid Volumes
1,613 BBLS HCL ACID

Fracture Treatments	
18,894,520 POUNDS OF SAND 485,897 BBLS OF FLUID	

Formation	Тор
SPRINGER	12814
MISSISSIPPIAN	14111
WOODFORD	14512

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

### Other Remarks

OCC - CORRECTED TOE PERFORATION DEPTH, API SUFFIX

### **Lateral Holes**

Sec: 34 TWP: 5N RGE: 6W County: GRADY

SW SE SE SW

29 FSL 2302 FWL of 1/4 SEC

Depth of Deviation: 13833 Radius of Turn: 658 Direction: 176 Total Length: 9837

Measured Total Depth: 24703 True Vertical Depth: 15165 End Pt. Location From Release, Unit or Property Line: 29

# FOR COMMISSION USE ONLY

1143322

Status: Accepted

January 08, 2020 2 of 2

