

Oklahoma Corporation Commission
 Oil & Gas Conservation Division
 Post Office Box 52000
 Oklahoma City, Oklahoma 73152-2000
 Rule 165: 10-3-25

Form 1002A

API No.: 35051244130001

Completion Report

Spud Date: October 02, 2018

OTC Prod. Unit No.: 051-225400-0-0000

Drilling Finished Date: November 08, 2018

1st Prod Date: April 13, 2019

Completion Date: April 13, 2019

Drill Type: HORIZONTAL HOLE

Well Name: JEANNIE 6-27X34H

Purchaser/Measurer:

Location: GRADY 27 5N 6W
 NW SW NW SE
 1879 FSL 2361 FEL of 1/4 SEC
 Latitude: 34.8746828 Longitude: -97.8191631
 Derrick Elevation: 0 Ground Elevation: 1148

First Sales Date:

Operator: GULFPORT MIDCON LLC 24020

3001 QUAIL SPRINGS PKWY
 OKLAHOMA CITY, OK 73134-2640

Completion Type	
X	Single Zone
	Multiple Zone
	Commingled

Location Exception	
Order No	
702551	

Increased Density	
Order No	
680412	
680413	

Casing and Cement							
Type	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT
CONDUCTOR	30			128			
SURFACE	13 3/8		J-55	1514		880	SURFACE
INTERMEDIATE	9 5/8		P-110	12732		985	8752
PRODUCTION	5 1/2		P-110HC	21885		1895	11469

Liner								
Type	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 21890

Packer	
Depth	Brand & Type
There are no Packer records to display.	

Plug	
Depth	Plug Type
There are no Plug records to display.	

Initial Test Data

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut-In Pressure	Choke Size	Flow Tubing Pressure
May 01, 2019	WOODFORD	631	59	13781	21839	4718	FLOWING	4073	32/64	

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: GAS

Spacing Orders

Order No	Unit Size
456941	640
701831	MULTIUNIT
446322	640

Perforated Intervals

From	To
15336	21740

Acid Volumes

984 GALLONS ACID

Fracture Treatments

281,611 BARRELS WATER, 14,118,104 POUNDS SAND

Formation	Top
WOODFORD	14890

Were open hole logs run? No

Date last log run:

Were unusual drilling circumstances encountered? No

Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 34 TWP: 5N RGE: 6W County: GRADY

SE SE SW SE

89 FSL 1631 FEL of 1/4 SEC

Depth of Deviation: 14622 Radius of Turn: 768 Direction: 170 Total Length: 6404

Measured Total Depth: 21890 True Vertical Depth: 15222 End Pt. Location From Release, Unit or Property Line: 89

FOR COMMISSION USE ONLY

1145277

Status: Accepted