Oklahoma Corporation Commission Oil & Gas Conservation Division Post Office Box 52000 Oklahoma City, Oklahoma 73152-2000

Rule 165: 10-3-25

OTC Prod. Unit No.: 051-226870-0-0000 Drilling Finished Date: September 21, 2019

1st Prod Date: July 29, 2020

Completion Date: February 27, 2020

Drill Type: HORIZONTAL HOLE

Min Gas Allowable: Yes

Well Name: JACQUEZ 4-18-19XHW Purchaser/Measurer: ENABLE MIDSTREAM

Location: GRADY 18 7N 5W First Sales Date: 7/29/2020

SW SW SW NE

2315 FNL 2608 FEL of 1/4 SEC Latitude: 35.081325 Longitude: -97.767482 Derrick Elevation: 1253 Ground Elevation: 1226

Operator: CONTINENTAL RESOURCES INC 3186

PO BOX 268870 20 N BROADWAY AVE

OKLAHOMA CITY, OK 73126-8870

Completion Type			Location Exception
Х	Single Zone		Order No
	Multiple Zone		713097
	Commingled		

Increased Density
Order No
700298
700297

Casing and Cement								
Туре	Size	Weight	Grade	Feet	PSI	SAX	Top of CMT	
SURFACE	9.63	40	J-55	1477		460	SURFACE	
PRODUCTION	5.5	23	P-110	20660		2565	SURFACE	

				Liner				
Туре	Size	Weight	Grade	Length	PSI	SAX	Top Depth	Bottom Depth
There are no Liner records to display.								

Total Depth: 20663

Pac	ker
Depth	Brand & Type
There are no Packe	er records to display.

Plug				
Depth	Plug Type			
There are no Plug	records to display.			

Initial Test Data

October 09, 2020 1 of 2

Test Date	Formation	Oil BBL/Day	Oil-Gravity (API)	Gas MCF/Day	Gas-Oil Ratio Cu FT/BBL	Water BBL/Day	Pumpin or Flowing	Initial Shut- In Pressure	Choke Size	Flow Tubing Pressure
Jul 31, 2020	WOODFORD	419	44.12	504	1203	3664	FLOWING	1599	40/64	834

Completion and Test Data by Producing Formation

Formation Name: WOODFORD

Code: 319WDFD

Class: OIL

Spacing Orders				
Order No	Unit Size			
621966	640			
713098	MULTIUNIT			

Perforated Intervals				
From	То			
12211	15397			
15427	20468			

Acid Volumes
1590 BBLS 15% HCI

Fracture Treatments
396,438 BBLS FLUID & 19,889,890 LBS OF SAND

Formation	Тор
WOODFORD	12211

Were open hole logs run? No Date last log run:

Were unusual drilling circumstances encountered? No Explanation:

Other Remarks

There are no Other Remarks.

Lateral Holes

Sec: 19 TWP: 7N RGE: 5W County: GRADY

SE SE SE SW

53 FSL 2539 FWL of 1/4 SEC

Depth of Deviation: 11530 Radius of Turn: 732 Direction: 181 Total Length: 8452

Measured Total Depth: 20663 True Vertical Depth: 12317 End Pt. Location From Release, Unit or Property Line: 53

FOR COMMISSION USE ONLY

1145181

Status: Accepted

October 09, 2020 2 of 2